

**Facility Name:** Utica Resource Operating, LLC – Miley Well Pad  
**Facility Location:** 39.85269, -81.4574, Wills Township, Ohio  
**Date of Inspection:** April 18, 2019

**APPENDIX A: DIGITAL IMAGE/VIDEO LOG**

<b>1. Inspector Name:</b> Victoria Nelson	<b>2. Dates of Inspection:</b> April 18, 2019
<b>3. Company/Facility Name:</b> Utica Resource Operating, LLC – Miley Well Pad	<b>4. Street Address, City, State:</b> 39.85269, -81.4574, Wills Township, Ohio
<b>5. Number of Images and Videos:</b> 9	<b>6. Archival Record Location:</b> C:\Users\Vnelson\OneDrive - Environmental Protection Agency (EPA)\MyCases\Utica Resource\Inspection Reports

Video Number	File Name	Date	Description of Video
1	MOV_2392.mp4	4/18/2019	Emissions from combustor stack
2	MOV_2393.mp4	4/18/2019	Emissions from 7H condensate tank header line - from ground level
3	MOV_2394.mp4	4/18/2019	Emissions from 7H condensate tank header line pressure relief device
4	MOV_2395.mp4	4/18/2019	Emissions from Tank 76277 thief hatch
5	MOV_2396.mp4	4/18/2019	Emissions from Tank 76278 header line pressure relief device

Image Number	File Name	Date and Time (Eastern Time)	Latitude and Longitude	Description of Image
1	P4180030.JPG	4/18/2019 12:43:39 PM	39.951389,  -81.434444	Staining and paraffin build-up at threaded connection and thief hatch at 1H condensate tank
2	P4180031.JPG	4/18/2019 12:44:35 PM	39.853056,  -81.456389	Staining and condensate droplets from header line pressure relief device at 7H condensate tank

**Facility Name:** Utica Resource Operating, LLC – Miley Well Pad

**Facility Location:** 39.85269, -81.4574, Wills Township, Ohio

**Date of Inspection:** April 18, 2019

3	P4180032.JPG	4/18/2019 12:45:49 PM	39.853056, -81.456389	Staining, paraffin build-up, and condensate droplets from thief hatch and threaded connection at 7H condensate tank
4	P4180033.JPG	4/18/2019 12:48:22 PM	39.853043, -81.456528	Oil sheen on collected water in tank battery containment area